



EXISTING ROOF
 REMOVE EXISTING FIBRE / CEMENT SLATES,
 BATTENS AND PARGING TO SLATES
 FIT NEW BREATHABLE ROOFING FELT
 TREATED SLATING BATTENS AND NEW
 FIBRE SLATES FIXED TO PATTERN TO
 MATCH EXISTING

ALL EXISTING DOOR AND WINDOWS TO
 BE LIGHTLY SANDED TO PROVIDE KEY
 FOR NEW 3 COAT PAINT APPLICATION.
 EARLY OR ORIGINAL IRONMONGERY TO
 BE RETAINED, LUBRICATED AND POLISHED,
 MODERN OR INAPPROPRIATE IRONMONGERY
 TO BE REPLACED NEW PERIOD PIECES TO
 MATCH EXISTING AS CLOSELY AS POSSIBLE.
 EXISTING SKIRTINGS TO BE LIGHTLY
 SANDED TO PROVIDE KEY FOR NEW 3
 COAT PAINT APPLICATION

THE DADO RAIL AROUND THE WALLS OF
 THE FORMER COURTROOM IS A SCROLL,
 MADE BY AN INLET MOULD RUN IN THE
 WALL PLASTER; THIS DECORATIVE
 FEATURE TO BE RETAINED AND
 PROTECTED FROM DAMAGE DURING THE
 PROPOSED WORKS.

THE CEILING OF THE FORMER JUDGE'S
 ROBING ROOM IS A MODERN
 PLASTERBOARD CEILING FIXED TO
 CEILING JOIST. THIS CEILING TO BE
 CHECKED FOR ITS STABILITY; ANY
 LOOSE OR INSECURED CEILING SLABS TO
 BE REPLACED / SECURED AND MADE
 GOOD AND ENTIRE CEILING DECORATED.

THE CEILING TO THE FORMER
 COURTROOM IS ALSO A MODERN
 PLASTERBOARD CEILING FIXED TO
 CEILING JOIST. THE CORNICE AROUND
 THE PERIMETER OF THE ROOM IS A
 LATHE-ON-PLASTER CEILING. (PROBABLY
 ORIGINAL)
 THIS CEILING TO BE
 CHECKED FOR ITS STABILITY; ANY
 LOOSE OR INSECURED CEILING SLABS TO
 BE REPLACED / SECURED AND MADE
 GOOD AND ENTIRE CEILING DECORATED.

THE CORNICE TO BE CHECKED FOR
 STABILITY, DECAY AND SECURITY AND TO
 BE CONSERVED AND REPAIRED
 ACCORDINGLY. REPAIR WATER DAMAGED
 CEILING AT SOUTH-EASTERN CORNER OF
 THE COURTROOM.

MANUFACTURES
 BRINGS ON
 RS

1000

GLAZED LINK BETWEEN
 EXISTING BUILDING AND
 PROPOSED EXTENSION

FLOOR
 REMOVE EXISTING 18mm PLYWOOD AND TIMBER FLOOR BOARDS
 REMOVE EXISTING WALL PLATE AND CHECK TASSSEL WALLS
 FIT DPC UNDER NEW WALL PLATE AND FIT NEW FLOOR BOARDS

DERFLOOR
 ER COMPLETE
 UFACTURERS SPEC ON

SECTION C-C
SCALE 1:50

SECTION C-C