

NOTES
 It is the contractors responsibility to check design levels and sizes for compliance. Any discrepancies or errors to be identified to the design team.


Topographical Survey Undertaken to obtain existing levels and dimensions of the site.

- KEY**
- Existing Foot Path
 - Existing Overhead Powerline
 - Indicative Tree Line

REVISION	DETAILS	BY	DATE	CHECKED

info@sportslabsconsult.com

**KNOCKLYON PARK
 TOPOGRAPHICAL SURVEY
 CONSTRUCTION OF A NEW ARTIFICIAL PITCH**



Date: 04/2023 Scale: 1:1000 @ A3	Job No. 3096	Drawn by: CH Checked by: GS
-------------------------------------	---------------------	--------------------------------